

PERSONAL SAFETY

- Comfort Particle Mask P3
- Hearing Protection
- Comfort Goggles
- Reusable Overall
- Safety Gloves

1 Sanding down the job area		<ul style="list-style-type: none"> ▶ 3M™ Hookit™ Cubitron™ II 120+ - 150+. ▶ Marking the sanding scratches - application of dry guide coat. 	
2 Fine sanding of the surface & feather edges		<ul style="list-style-type: none"> ▶ 3M™ Hookit™ Cubitron™ II 220+ - 240+. ▶ Refine previous sanding scratches which reduces the possibility of solvents from the body filler penetrating into the OEM paint layers. If this happens it can lead to surface swelling around the repair. 	
3 Sanding the body filler		<ul style="list-style-type: none"> ▶ 3M™ Hookit™ Cubitron™ II 150+ - 240+. ▶ Initial shaping of the body filler. ▶ Ensure that you use dust extraction. ▶ Identify and highlight sanding scratches through the application of dry guide coat. 	
4 Pre-sanding of edges and borders		<ul style="list-style-type: none"> ▶ 3M™ Hookit™ Flexible Abrasive Sheets P800 - P1000. Note: For maximum process safety. 	
5 Fine sanding of the surface & feather edges		<ul style="list-style-type: none"> ▶ 3M™ Hookit™ Cubitron™ II 320+. ▶ It is advisable to work with a soft interface pad when sanding curved areas. Tip: The choice of the fine grit has to be adjusted to the solvent sensitivity of the original paint. The higher the solvent sensitivity of the original paint, the finer the sanding before primer application. 	
6 Flat sanding of the primer above the body filler area		<ul style="list-style-type: none"> ▶ 3M Hookit™ Hand Block and 3M Abrasives 320+ - 400+. ▶ Highlight the texture and structure of the primer using dry guide coat. ▶ For best result and the most efficient process always use dust extraction. 	
7 Pre-sanding of edges and borders		<ul style="list-style-type: none"> ▶ 3M™ Hookit™ Flexible Abrasive Sheets P800-P1000 Note: For maximum process safety. ▶ Identify and highlight sanding scratches through the application of dry guide coat. 	
8 Large-area face grinding of the primer		<ul style="list-style-type: none"> ▶ Eccentric sanding with 3M Abrasives 400+ - P500. ▶ For critical colours use a 3M™ Hookit™ Flexible Foam Disc P600 as a last sanding step after 400+. ▶ Dedusting of the surface with 3M™ Scotch-Brite™ Abrasives Discs. Tip: It is advisable to work with a soft interface pad sanding curved areas. 	
9 Blending in to adjacent parts		<ul style="list-style-type: none"> ▶ 3M™ Hookit™ Flexible Foam Disc P800 - P1000 ▶ Prepare adjacent areas of the OEM clearcoat. Note: For maximum process safety. 	