




Quick Term II


Silicone Rubber Termination Kits for Shielded Cables

Instruction Sheet


Tape Shield



Wire Shield



UniShield™



UniShield™ is a registered trademark of Cablec Corporation

Kit No.	Cable Insulation O.D. Range	Cable Jacket O.D. Range	Conductor Size Range (AWG & kcmil)	
			25 kV	35 kV
5696K	0.84 - 1.33 in. (21,3 - 33,8 mm)	1.00 - 1.60 in. (25,4 - 40,6 mm)	1/0 - 250	2 - 3/0
5697K	1.10 - 1.65 in. (27,9 - 41,9 mm)	1.30 - 1.90 in. (33,0 - 48,3 mm)	300 - 500	4/0 - 400
5698K	1.30 - 1.95 in. (33,0 - 49,5 mm)	1.50 - 2.40 in. (38,1 - 61,0 mm)	600 - 1250	500 - 1000

Table 1

Kit Contents:

Each kit contains sufficient quantities of the materials to make three (3) terminations.

- 3 Silicone Rubber Terminations
- 3 Mechanical Ground Strap Assemblies
- 3 Strips of Scotch™ 24 Shielding Tape
- 3 Strips of Mastic
- 1 Roll Scotch™ 13 Semi-Conducting Tape
- 1 Roll of Scotch™ 70 Silicone Rubber Tape
- 3 Packs of Silicone Grease
- 1 Scotch™ Brand A-2 Cable Preparation Kit
- 1 Illustrated instruction sheet



Technical Information:

For use on Tape or Wire Shielded and UniShield™ Cables
Copper or Aluminum Conductors

IEEE Std. No. 48-1990
Class I Termination
34.5 kV Class, 200 kV BIL

Cable Size Range:
25 kV - 1/0 AWG - 1250 kcmil
35 kV - 2 AWG - 1000 kcmil

3M Quick Term II Silicone Rubber Terminations for Shielded Cables

5696K
5697K

5698K

Number of Pages: 6

Scale: Not to Scale

Issue Date: 11/17/97

Issue: A

78-8111-0851-9

Instructions For Tape Shielded Cable, 25 and 35 kV

Note: The Scotch™ 24 Electrical Shielding Tape in kit will not be used for terminating tape shielded cable.

A. PREPARE CABLE

1. Check to be sure cable size fits within kit range as shown in **Table 1** on page 1.
2. Remove jacket, metallic tape shielding, semi-con and insulation as shown in **Figure 1** and **Table 2**. (Be sure to allow for depth of lug barrel [B].)
3. Wrap 2 highly stretched half-lapped layers of Scotch™ 13 Semi-Conducting Tape over the ends of the tape shield and semi-con. Start and end taping $\frac{3}{4}$ " (19 mm) onto tape shield leaving a smooth, even leading edge $\frac{1}{4}$ " (6 mm) onto cable insulation (**Figure 2**).




Figure 1

Kit No.	Dimension [A]	Dimension [B]
5696K	18" (457 mm)	Depth of Terminal Lug Barrel
5697K	18 1/2" (470 mm)	
5698K		

Table 2

4. Clean cable using standard practice:
 - a. Wipe the cable insulation with one of the solvent saturated pads from the Scotch™ A-2 Cable Preparation Kit. Do not allow solvent to touch semi-con.
 - b. If abrasive must be used, use only 120 grit aluminum oxide that is provided with A-2 kit.

B. Install Ground Strap

1. Unwrap 1" to 2" (25 to 50 mm) of coil.
2. Lay the ground strap along cable with extended coil facing downward (away from you) (**Figure 2**). NOTE: Coil should be in contact with cable shielding and as close as possible to the cable jacket end.




Figure 2

3. Hold the strap in place with thumb. Pull the coil around the cable allowing it to unwrap and rewrap around the shielding and itself (**Figure 3**). NOTE: Cinch (tighten) the applied coil after final wrap.




Figure 3

4. Sealing the ground strap:
 - a. Cut 2 pieces of mastic $1\frac{1}{2}$ " (38 mm) long and remove liner.
 - b. Wrap 1 piece under grounding strap and as close as possible to cable jacket end. Stretch mastic to maintain low profile. Push strap into mastic and wrap second piece over ground strap (**Figure 4**).




Figure 4

5. Wrap one half-lapped layer of highly stretched vinyl tape (e.g. Scotch™ Super 33+ Tape, not supplied in kit) over mastic strip and ground strap coil, to edge of previously applied 13 tape (**Figure 5**).




Figure 5

C. Install Termination

1. Place a marker tape $3\frac{3}{4}$ " (95 mm) back from the insulation end of the 13 Tape (**Figure 5**).
2. Cover the edge of the 13 Tape with a liberal coating of silicone grease (**Figure 5**). NOTE: On this product, the silicone grease does not serve as a lubricant. It must be used to fill the step at the 13 Tape leading edge. The silicone grease may also be used to fill in cable surface defects and can be applied over the ground strap seal to aid in core removal (step C-4).
3. Slide the termination body onto the cable, aligning the base with previously applied marker tape (**Figure 6**).




Figure 6

4. Remove termination core unwinding counter-clockwise starting with the loose end. Make sure the termination body is butted up to the edge of the marker tape (**Figure 6**). TIP: An occasional tug of the core strand while unwinding will aid in core removal.

D. Install Lug and Seal Terminal Area

1. Install terminal lug per manufacturer's direction. See page 5 or 6 if 3M lugs are used.
2. Wrap 4 half-lapped layers of Scotch™ 70 Silicone Rubber Tape over the lug and onto the insulator for 1" (25 mm) (**Figure 7**). TAPING HINT: Apply first 3 layers with moderate tension. Apply last lap with zero or very little tension.
3. If lug is not used, solder block conductor and wrap 4 half-lapped layers of 70 Tape from the solder block to 1" (25 mm) onto the insulator, using the Taping Hint in step D-2.




Figure 7

Instructions For Wire Shielded Cable, 25 and 35 kV

A. PREPARE CABLE

1. Check to be sure cable size fits within kit range as shown in **Table 1** on page 1.
2. Remove jacket as shown in **Figure 1** and **Table 2**. (Be sure to allow for depth of lug barrel [B].)




Figure 1

Kit No.	Dimension [A]	Dimension [B]
5696K	18" (457 mm)	Depth of Terminal Lug Barrel
5697K	18½" (470 mm)	
5698K		

Table 2

3. Wrap 2 wraps of Scotch 24 Shielding Tape over shielding wires at jacket edge. Cut off excess 24 Tape (Figure 1).
4. Bend shielding wires back over 24 Tape and cut excess off at jacket edge (Figure 1).
5. Remove semi-con as shown (Figure 1).
6. Remove cable insulation for length of terminal lug barrel, dimension [B] (Table 2).
7. Wrap 2 highly stretched half-lapped layers of Scotch 13 Semi-Conducting Tape over end of cable semi-con. Start and end taping ¾" (19 mm) onto cable semi-con, leaving a smooth, even leading edge ¼" (6 mm) onto cable insulation (Figure 2).
8. Clean cable using standard practice:




Figure 2

- a. Wipe the cable insulation with one of the solvent saturated pads from the Scotch™ A-2 Cable Preparation Kit. Do not allow solvent to touch semi-con.
- b. If abrasive must be used, use only 120 grit aluminum oxide that is provided with A-2 kit.

B. Install Ground Strap

1. Unwrap 1" to 2" (25 to 50 mm) of coil.
2. Lay the ground strap along cable with extended coil facing downward (away from you) (Figure 2). **NOTE:** Coil should be in contact with cable shielding and as close as possible to the cable jacket end.
3. Hold the strap in place with thumb. Pull the coil around the cable allowing it to unwrap and rewrap around the shielding and itself (Figure 3). **NOTE:** Cinch (tighten) the applied coil after final wrap.




Figure 3

4. Sealing the ground strap:
 - a. Cut 2 pieces of mastic 1½" (38 mm) long and remove liner.
 - b. Wrap 1 piece under grounding strap and as close as possible to cable jacket end. Stretch mastic to maintain low profile. Push strap into mastic and wrap second piece over ground strap (Figure 4).




Figure 4

5. Wrap one half-lapped layer of highly stretched vinyl tape (e.g. Scotch™ Super 33+ Tape, not supplied in kit) over mastic strip and ground strap coil, to edge of previously applied 13 tape (Figure 5).




Figure 5

C. Install Termination

1. Place a marker tape 3-¾" (95 mm) back from the end of the 13 Tape (Figure 5).
2. Cover the edge of the 13 Tape with a liberal coating of silicone grease (Figure 5). **NOTE:** On this product, the silicone grease does not serve as a lubricant. It must be used to fill the step at the 13 Tape leading edge. The silicone grease may also be used to fill in cable surface defects and can be applied over the ground strap seal to aid in core removal (step C-4).
3. Slide the termination body onto the cable, aligning the base with previously applied marker tape (Figure 6).
4. Remove termination core unwinding counter-clockwise




Figure 6

starting with the loose end. Make sure the termination body is butted up to the edge of the marker tape (Figure 6). **TIP:** An occasional tug of the core strand while unwinding will aid in core removal.

D. Install Lug and Seal Terminal Area

1. Install terminal lug per manufacturer's direction. See page 5 or 6 if 3M lugs are used.
2. Wrap 4 half-lapped layers of Scotch™ 70 Silicone Rubber Tape over the lug and onto the insulator for 1" (25 mm) (Figure 7). **TAPING HINT:** Apply first 3 layers with moderate tension. Apply last lap with zero or very little tension.
3. If lug is not used, solder block conductor and wrap four half-lapped layers of 70 Tape from the solder block to 1" (25 mm) onto the insulator, using the Taping Hint in step D-2.




Figure 7

Instructions For UniShield™ Cable, 25 and 35 kV

Note: The ground straps and the Scotch™ 24 Electrical Shielding Tape in the kit will not be used for terminating UniShield™ cable.

A. PREPARE CABLE

1. Check to be sure cable size fits within kit range as shown in **Table 1** on page 1.
2. Remove drain wires from semi-con jacket for distance [A] + [B] + 3/4" (19 mm) as shown in **Figure 1** and **Table 2**. (Be sure to allow for depth of lug barrel [B].)




Figure 1

Kit No.	Dimension [A]	Dimension [B]
5696K	17 1/2" (445 mm)	Depth of Terminal Lug Barrel
5697K	18" (457 mm)	
5698K		

Table 2

3. Install hose clamp at dimension [A] + [B] and cut 80% through jacket (**Figure 1**, **Table 2**).
4. Remove jacket by pulling against hose clamp (**Figure 1**). DO NOT BELL SEMI-CON JACKET. NOTE: If double-layer semi-con jacket is difficult to remove, first score it longitudinally by cutting along grooves left by drain wires.
5. Remove cable insulation for length of terminal lug barrel.
6. Remove hose clamp.
7. Bend drain wires away from cable (**Figure 2**).
8. Wrap 1 layer of the mastic strip provided around the cable at the base of the drain wires, 3/4" (19 mm) from the jacket cut-off.




Figure 2

Stretch the mastic slightly when applying. Cut off excess (**Figure 2**).

9. Bend the drain wires over the mastic and press into the mastic (**Figure 3**). Overwrap mastic with 2 layers of highly stretched vinyl tape (e.g. Scotch™ Super 33+ Tape, not supplied in kit).
10. Wrap two highly stretched half-lapped layers of Scotch™ 13 Semi-Conducting Tape over end of cable semi-con jacket.




Figure 3

Start and end taping at drain wires, leaving a smooth, even leading edge 1" (25 mm) onto cable insulation (**Figure 4**).




Figure 4

11. Clean cable, using standard practice:
 - a. Wipe the cable insulation with one of the solvent saturated pads from the Scotch A-2 Cable Preparation Kit. Do not allow solvent to touch semi-con.
 - b. If abrasive must be used, use only 120 grit aluminum oxide that is provided with A-2 Kit.

B. Install Termination

1. Place a marker tape 3 1/2" (89 mm) back from the insulation end of the 13 Tape (**Figure 5**).




Figure 5

2. Cover the edge of the 13 Tape with a liberal coating of silicone grease (**Figure 5**). NOTE: On this product, the silicone grease does not serve as a lubricant. It must be used to fill the step at the 13 Tape leading edge. The silicone grease may also be used to fill in cable surface defects and can be applied over the ground strap seal to aid in core removal (step B-4).
3. Slide the termination body onto the cable, aligning the base with previously applied marker tape (**Figure 6**).




Figure 6

4. Remove termination core unwinding counter-clockwise starting with the loose end. Make sure the termination body is butted up to the edge of the marker tape (**Figure 6**). TIP: An occasional tug of the core strand while unwinding will aid in core removal.

C. Install Lug and Seal Terminal Area

1. Install terminal lug per manufacturer's direction. See page 5 or 6 if 3M lugs are used.
2. Wrap 4 half-lapped layers of Scotch™ 70 Silicone Rubber Tape over the lug and onto the insulator for 1" (25 mm) (**Figure 7**). TAPING HINT: Apply first 3 layers with moderate tension. Apply last lap with zero or very little tension.
3. If lug is not used, solder block conductor and wrap four half-lapped layers of 70 Tape from the solder block to 1" (25 mm) onto the insulator, using the Taping Hint in step C-2.




Figure 7

**Crimping Information for
3M Stem Connectors
Copper/Aluminum**




CRIMPING TABLE FOR 3M STEM TYPE CONNECTOR

Conductor Size	3M Connector Number	Recommended Crimping Tools				
		Manufacturer	Mechanical Tool	Die (No. of Crimps)	Hydraulic Tool	Die (No. of Crimps)
2 AWG Solid 1 AWG, 2 AWG 1/0 AWG	SC0002	Burndy	MD6	BG(4), W243(4)	Y35, Y39, Y45 **	U25ART (2), U243 (2)
	SC0001	Kearny	0-51, 0-52	5/8-1(4)	12, 20, 40 TON	5/8-1(4)
	SC0010	T & B	TBM 8	Olive (2)	TBM 15	50* (2)
		Anderson	—	—	VC 6	Universal (2)
2/0 AWG 3/0 AWG 4/0 AWG	SC0020	Burndy	MD6	W669 (0) 840 (5)*	Y35, Y39, Y45 **	U28ART (2)
	SC0030	Kearny	0-51, 0-52	840 (5) *	WH-1, WH-2	840 (2)
	SC0040	T & B	TBM 8	White (4)	TBM 15	66 (3)
		Anderson	—	—	VC 6	Universal (2)


Tooling Index

**Lug and Crimping Information for
Scotchlok™ Copper/Aluminum Lugs**

**40016 thru 40079
One hole**



**40132 thru 40178
Two hole**



Cable Size AWG/ kcmil	Stud Size (in.)	Scotchlok™ Lug Number	CRIMPING TOOL-DIE SETS (NO. OF CRIMPS)												
			Burndy Corporation					Thomas & Betts Corporation				Square D Co. Anderson Div.		ITT Black- burn Co.	Kearney Nat'l Div.
			MD6	MY29	Y34A	Y35, 39, 45*, 46*	** Y1000	TBM 5	TBM 8	TBM 12	TBM 15	VC6-3** VC6-FT**	VC8C	OD58	TYPE 0
6	5/16	40016	W161 (1)	6 AWG (1)	A6CAB (1)	U6CABT (1)	(1)	Grey (1)	Grey (1)	—	29 (1)	(1)	—	BY19 (3)	J (3)
4	5/16	40020	W162 (3)	4 AWG (1)	A4CAB (1)	U4CABT (1)	(1)	Green (2)	Green (2)	—	37 (1)	(1)	—	BY53 (3)	P (3)
2	3/8	40024	W163(3)	2 AWG (1)	A2CAB (1)	U2CABT (1)	(1)	Pink (2)	Pink (2)	—	42H (2)	(1)	—	BY23 (3)	½ (3)
	1/2	40025	W163(3)	2 AWG (1)	A2CAB (1)	U2CABT (1)	(1)	Pink (2)	Pink (2)	—	42H (2)	(1)	—	BY23 (3)	½ (3)
1	3/8	40028	W163(3)	1 AWG (1)	A1CAR (1)	U1CART (1)	(1)	Gold (2)	Gold (2)	—	45 (1)	(1)	—	BY23 (3)	½ (3)
	1/2	40029	W163(3)	1 AWG (1)	A1CAR (1)	U1CART (1)	(1)	Gold (2)	Gold (2)	—	45 (1)	(1)	—	BY23 (3)	½ (3)
1/0	3/8	40032	W241(3)	1/0 (1)	A25AR (1)	U25ART (1)	(1)	Tan (2)	Tan (2)	—	50 (1)	(1)	—	BY25 (3)	5/8-1 (3)
	1/2	40033	W241(3)	1/0 (1)	A25AR (1)	U25ART (1)	(1)	Tan (2)	Tan (2)	—	50 (1)	(1)	—	BY25 (3)	5/8-1 (3)
	3/8	40132	W241(3)	1/0 (1)	A25AR (1)	U25ART (1)	(1)	Tan (2)	Tan (2)	—	50 (1)	(1)	—	BY25 (3)	5/8-1 (3)
2/0	1/2	40037	BG (4)	2/0 (1)	A26AR (2)	U26ART (2)	(1)	Olive (2)	Olive (2)	—	54H (2)	(2)	—	BY31C (3)	5/8-1 (3)
	1/2	40137	BG (4)	2/0 (1)	A26AR (2)	U26ART (2)	(1)	Olive (2)	Olive (2)	—	54H (2)	(2)	—	BY31C (3)	5/8-1 (3)
3/0	1/2	40041	W166 (4)	3/0 (1)	A27AR (2)	U27ART (2)	(1)	Ruby (2)	Ruby (2)	—	60 (2)	(2)	—	—	737 (3)
	1/2	40141	W166 (4)	3/0 (1)	A27AR (2)	U27ART (2)	(1)	Ruby (2)	Ruby (2)	—	60 (2)	(2)	—	—	737 (3)
4/0	1/2	40045	W660 (4)	4/0 (2)	A28AR (2)	U28ART (2)	(1)	—	White (4)	—	66 (4)	(2)	—	BY35C (4)	840 (4)
	5/8	40046	W660 (4)	4/0 (2)	A28AR (2)	U28ART (2)	(1)	—	White (4)	—	66 (4)	(2)	—	BY35C (4)	840 (4)
	1/2	40145	W660 (4)	4/0 (2)	A28AR (2)	U28ART (2)	(1)	—	White (4)	—	66 (4)	(2)	—	BY35C (4)	840 (4)
250	1/2	40049	W249 (3)	—	A29AR (2)	U29ART (2)	(1)	—	—	71H (4)	71H (2)	(3)	—	—	—
	5/8	40050	W249 (3)	—	A29AR (2)	U29ART (2)	(1)	—	—	71H (4)	71H (2)	(3)	—	—	—
	1/2	40149	W249 (3)	—	A29AR (2)	U29ART (2)	(1)	—	—	71H (4)	71H (2)	(3)	—	—	—
300	1/2	40053	—	—	A30AR (2)	U30ART (2)	(1)	—	—	76H (4)	76 (2)	(3)	—	—	—
	1/2	40153	—	—	A30AR (2)	U30ART (2)	(1)	—	—	76H (4)	76 (2)	(3)	—	—	—
350	1/2	40056	—	—	—	U31ART (2)	(1)	—	—	87H (4)	87H (3)	(3)	—	—	—
	5/8	40057	—	—	—	U31ART (2)	(1)	—	—	87H (4)	87H (3)	(3)	—	—	—
	1/2	40156	—	—	—	U31ART (2)	(1)	—	—	87H (4)	87H (3)	(3)	—	—	—
400	1/2	40160	—	—	—	U32ART (4)	(1)	—	—	94H (4)	94H (4)	—	(2)	—	—
500	5/8	40067	—	—	—	U34ART (4)	(1)	—	—	106H (4)	106H (3)	—	(2)	—	—
	1/2	40166	—	—	—	U34ART (4)	(1)	—	—	106H(4)	106H (3)	—	(2)	—	—
600	1/2	40170	—	—	—	U36ART (4)	(1)	—	—	—	115H (3)	—	(3)	—	—
750	5/8	40073	—	—	—	U39ART (4)	(1)	—	—	—	125H (5)	—	(3)	—	—
	1/2	40172	—	—	—	U39ART (4)	(1)	—	—	—	125H (5)	—	(3)	—	—
1000	5/8	40079	—	—	—	S44ART (4)	(1)	—	—	—	140H (4)	—	(3)	—	—
	1/2	40178	—	—	—	S44ART (4)	(1)	—	—	—	140H (4)	—	(3)	—	—

* Y45 and Y46 accept all Y35 dies ("U" series). For Y45 use PT6515 adapter. For Y46 use PUADP adapter.

** Anderson VC6-3, VC6-FT, VC8C and Burndy Y1000 require no die set.

Tooling Index

Lug and Crimping Information for Scotchlok™ Copper Lugs										
30014 thru 30045 One hole			31036 thru 31068 One hole - long barrel				31145 thru 31178 Two hole			
			CRIMPING TOOL-DIE SETS (AND NO. OF CRIMPS)							
Cable Size AWG/kcmil	Stud Size (in.)	Scotchlok Copper Lug Number	Burdmy Corporation				Thomas & Betts Corporation			Square D Co. Anderson Div.
			MD6	MY29	Y34A	Y35, Y39, Y45*, Y46*	TBM5	TBM8	TBM15	VC6-3, VC6-FT**
6	10 1/4 5/16	30014 30015 30016	—	6 AWG (1)	—	U5CRT (1)	Blue (1)	Blue (1)	—	Universal (1)
4	10 1/4 3/8	30018 30019 30021	W161 (1)	4 AWG (1)	A4CR (1)	U4CRT (1)	Grey (1)	Grey (1)	—	Universal (1)
2	1/4 5/16 3/8	30022 30023 30024	W162 (2)	2 AWG (1)	A2CR (1)	U2CRT (2)	Brown (1)	Brown (1)	33 (1)	Universal (2)
1	5/16 3/8	30027 30028	—	1 AWG (1)	A1CR (1)	U1CRT (2)	Green (1)	Green (1)	37 (1)	Universal (2)
1/0	5/16 3/8	30031 30032	W163 (2)	1/0 (1)	A25R (1)	U25RT (1)	Pink (2)	Pink (2)	42H (2)	Universal (1)
2/0	3/8 3/8	30036 31036	W241 (2) W241 (3)	2/0 (1) 2/0 (2)	A26R (1) A26R (2)	U26RT (2) U26RT (3)	Black (2) Black (3)	Black (2) Black (3)	45(1) 45 (2)	Universal (1) Universal (2)
3/0	1/2 1/2	30041 31041	W243 (2) W243 (3)	3/0 (1) 3/0 (2)	A27R (1) A27R (2)	U27RT (2) U27RT (3)	Orange (2) Orange (3)	Orange (2) Orange (3)	50 (1) 50 (2)	Universal (2) Universal (3)
4/0	1/2 1/2 1/2	30045 31045 31145	BG (3) BG (4) BG (4)	4/0 (1) 4/0 (2) 4/0 (2)	A28R (2)	U28RT (2) U28RT (3) U28RT (3)	Purple (2) Purple (3) Purple (3)	Purple (2) Purple (3) Purple (3)	54H (2) 54H (3) 54H (3)	Universal (2) Universal (3) Universal (3)
250	1/2 1/2	31049 31149	W166 (4)	250 (2)	A 29R (2)	U29RT (3)	Yellow (2)	Yellow (2)	62 (2)	Universal (2)
300	1/2 1/2	31053 31153	—	—	A30R (2)	U30RT (3)	—	White (3)	66 (3)	Universal (3)
350	1/2 1/2	31056 31156	—	—	A31R (2)	U31RT (3)	—	Red (4)	71H (4)	—
400	1/2 1/2	31060 31160	—	—	A32R (2)	U32RT (3)	—	Blue (4)	76H (4)	—
500	1/2 5/8 1/2	31066 31067 31166	—	—	A34R (2)	U34RT (3)	—	Brown (4)	87H (4)	—
600	1/2 1/2	31068 31168	—	—	—	U36RT (3)	—	Green (4)	94H (4)	—
750	1/2	31172	—	—	—	Y39, Y45, Y46: U39RT (5)	—	—	106H (4)	—
1000	1/2	31178	—	—	—	Y45: S44RT (6) Y46: P44RT(6)	—	—	125H (4)	—

'3M', 'Scotch' and 'Scotchcast' are trademarks of 3M

Important Notice

All statements, technical information and recommendations related to the Seller's products are based on information believed to be reliable, but the accuracy or completeness thereof is not guaranteed. Before utilizing the product, the user should determine the suitability of the product for its intended use. The user assumes all risks and liability whatsoever in connection with such use.

Any statements or recommendations of the Seller which are not contained in the Seller's current publications shall have no force or effect unless contained in an agreement signed by an authorized officer of the Seller. The statements contained

herein are made in lieu of all warranties expressed or implied, including but not limited to the implied warranties of merchantability and fitness for a particular purpose which warranties are hereby expressly disclaimed.

SELLER SHALL NOT BE LIABLE TO THE USER OR ANY OTHER PERSON UNDER ANY LEGAL THEORY INCLUDING BUT NOT LIMITED TO NEGLIGENCE OR STRICT LIABILITY, FOR ANY INJURY OR FOR ANY DIRECT OR CONSEQUENTIAL DAMAGES SUSTAINED OR INCURRED BY REASON OF THE USE OF ANY OF THE SELLER'S PRODUCTS THAT WERE DEFECTIVE.



Electrical Products Division

6801 River Place Blvd.
Austin, TX 78726-9000

Litho in USA
© 1997 3M
78-8111-0851-9 (A)