

# Welding

Oh, and a word of advice.  
You're supposed to wear the  
respirator underneath  
your welding shield...



## PPE typically used when welding:



3M™  
Speedglas™  
SL Welding  
Shield

+



Welding Fume  
Respirator

+



Welding  
protective  
clothing

## Items unsuitable for welding:



Nuisance dust  
mask

Welding produces lung damaging metal fumes.  
Wear respiratory protection as well as a welding shield.

**Protect Yourself.**

**3M**