

Welding and Spark Protection

1



Clean

Clean part with soap and water, followed by a VOC compliant surface cleaner.

2



Vertical Surface

Apply welding and spark deflection paper to vertical surfaces.

3



Horizontal Surface

Protect horizontal surfaces using cloth welding drape.

Visit 3MCollision.com for more SOPs and videos

Product List

Meguiar's® Shampoo Plus,
1gallon, PN D1101



Meguiar's® Citrus Power
Cleaner Plus, 1gallon,
PN D10701



3M™ Welding and
Spark Deflection
Paper, PN 05916



3M™ Welding and
Spark Deflection
Dispenser, PN 05912



3M™ High Performance
Welding Drape, PN 05919



Think About Your Health

3M™ E-A-R™ Skull Screws™
Ear Plug, PN P1300



3M™ Half Facepiece
Respirator, PN 07182



3M™ Virtua™ Protective
Eyewear, PN 11326

