



October 2, 2009

Mr. Mark Lund
3M Company
3M Center Bldg. 207-1W-02
St. Paul, MN 55144-1000

Our Reference: File R9700 / Project 09NK13180

Subject: Interchangeability of FireBarrier 20A Duct Wrap/Collars with FireBarrier 615 Duct Wrap/Collars and FireBarrier 615+ Duct Wrap/Collars

Dear Mark:

This is to advise you that we have completed the Referenced Project to determine the suitability of using any combination of the three products within the systems for which the material is currently listed for use in. The system for which all three materials are currently listed are Ventilation System Nos. V-20 and V-27 and Through-Penetration Firestop System Nos. C-AJ-1473, C-AJ-7096, F-A-1057, F-C-7054, W-J-7104, W-L-1323 and W-L-7180. Based on the testing conducted under Project 08CA60717, it was determined that the performance of the FireBarrier 615 duct wrap and collars was equivalent to that of the FireBarrier 20A duct wrap and collars. A subsequent investigation conducted under Project 09CA33125 determined that the performance of the FireBarrier 615+ duct wrap and collars was equivalent to that of the FireBarrier 615 duct wrap and collars. Based on the facing materials used with each of the duct wrap and collars, it was determined that any of the three collars could be used with any of the three duct wraps. For instance, the use of the FireBarrier 20A collars with the FireBarrier 615 or 615+ duct wraps would be suitable and would not adversely affect the ratings of the systems, providing that the materials used comply with the minimum thickness specified in the individual system.

Only those products which properly bear the Laboratory's Mark are considered as Listed or Classified by Underwriters Laboratories Inc. Any information and documentation involving UL Mark services are provided on behalf of Underwriters Laboratories Inc, (UL) or any authorized licensee.

Should you need any further assistance, please do not hesitate to contact us.

Very truly yours,

STEVEN J. HOFFMAN
Staff Engineer
Fire Protection Division

Reviewed by:

ALEC HAUSER
Staff Engineer
Fire Protection Division