

June 29, 2016
 Issue Number: 935

Product Change Notice: 3M™ D-Sub Plug, 8200 Series & 3M™ D-Sub Socket, 8300 Series

To Our Valued Customers:

Effective immediately, 3M has changed the manufacturing location of **3M™ D-Sub Plug, 8200 Series and 3M™ D-Sub Socket, 8300 Series**. This is a manufacturing location change only, there is no change to the product, which will continue to meet specifications. Labeling will change to reflect the change in manufacturing location.

Please note there is a change to 3M stock numbers for the new manufacturing location, detailed in the table below:

3M Part Number	Previous Stock Number	Replaced by New Stock Number	3M Part Number	Previous Stock Number	Replaced by New Stock Number
8209-6000	DE610012127	UU004886667	8309-6000	DE610012648	UU004869804
8209-6003	DE610012309	UU004858310	8309-6003	DE610012655	UU004869929
8209-6004	DE610012366	UU004886675	8309-6009	DE610012663	UU004887459
8209-6009	DE610012135	UU0048868723	8309-7009	DE610012671	UU004887343
8209-7009	DE610012150	UU004886683	8309-8000	DE610012689	UU004870364
8209-8000	DE610012267	UU004868756	8309-8003	DE610012697	UU004887350
8209-8003	DE610012358	UU004869713	8309-8009	DE610012705	UU004869945
8209-8009	DE610012275	UU004869721	8315-6000	DE610012713	UU003114863
8215-6000	DE610012168	UU003113162	8315-6003	DE610012721	UU003113121
8215-6003	DE610012317	UU003113139	8315-6009	DE610012739	UU003113147
8215-6009	DE610012176	UU003112909	8315-8000	DE610012754	UU003115290
8215-7009	DE610012192	UU003117429	8315-8009	DE610012770	UU003113154
8215-8000	DE610012200	UU003114855	8325-6000	DE610012788	UU004887368
8215-8009	DE610012283	UU003113113	8325-6003	DE610012796	UU004869952
8225-6000	DE610012010	UU004869739	8325-6009	DE610012812	UU004870372
8225-6003	DE610012325	UU004886691	8325-7009	DE610012820	UU004887376
8225-6009	DE610012036	UU004869747	8325-8000	DE610012838	UU004887384
8225-8000	DE610012119	UU004869754	8325-8003	DE610012846	UU004870380
8225-8003	DE610012606	UU004886709	8325-8009	DE610012853	UU004870398
8225-8009	DE610012101	UU004869762	8337-6000	DE610012861	UU004887392
8237-6000	DE610012218	UU004887319	8337-6003	DE610012879	UU004887400
8237-6003	DE610012333	UU004887327	8337-6009	DE610012887	UU004870406
8237-6009	DE610012226	UU004869770	8337-8000	DE610012895	UU004887418
8237-8000	DE610012291	UU004887335	8337-8003	DE610012929	UU004887426
8237-8009	DE610012259	UU004869788	8337-8009	DE610012903	UU004887434
8250-6005	DE610006699	UU004869796	8350-6005	DE610006715	UU004870810

This notification affects all of the 3M product part numbers on tech sheets TS-0234 and TS-0235. Thank you for your understanding and continued partnership with 3M.

Sincerely,
 Jo Burns | jburns2@mmm.com
 3M Electronics Materials Solutions Division
 Interconnect Products, European Marketing