



Date: 10/1/2018
To: All Current and Potential ProFirst Certified Collision Centers
From: Scott Kaboos / National Assistant Manager
Subject: Replacement Adhesive

American Honda has recently updated its recommendation for adhesives on certain model vehicles. If you are repairing a Honda or Acura vehicle and find a recommendation in the Body Repair Manual for L&L L-0504 adhesive, formerly only available from Honda and Acura dealers, we are now recommending 3M 7333 Impact Resistant Structural Adhesive instead. Honda and Acura dealers will be discontinuing the L&L product and it will no longer be available.

Attached is documentation on the replacement product 3M 7333 Impact Resistant Structural Adhesive and an example from the Body Repair Manual where the replacement product should be used.

Thank you for your commitment to proper and safe repairs. Should you have any other questions, please contact your Collision Market Manager (CMM).

New Product Recommendation – Applies to all Honda and Acura Vehicles that previously recommended L-0504 Adhesive



Body Repair News

September 2018

Version 1

Structural Adhesive for Body Component Replacement

Body component replacement procedures for some models require the use of a 2-part epoxy adhesive, L&L Products L-0504 (P/N: 08712-0011).

This adhesive is no longer available. Instead, use this alternative adhesive.

Description	Part Number
3M Impact Resistant Structural Adhesive	07333



This adhesive is commercially available from any materials jobber.

**New Product Recommendation – Example of when to apply
3M 7333 Impact Resistant Structural Adhesive rather than
previously recommended L-0504 Adhesive.**

11. Apply the adhesive (A) to the bulkhead (B) of the front pillar complete (C).
Adhesive: L&L Product L-0504, or equivalent
NOTE: See the adhesive manufacturer's instructions for details.

