

# Product Safety Recall



## 3M™ DBI-SALA® Self-Rescue Descent Systems

P/N 3320030, 3320031 & 3320037

3M Item ID: 70007650362, 70007650370, 70007649497

Sold prior to September 2020

**Defect:** Cracking due to embrittlement of the plastic pool used to hold the lifeline rope of the 3M™ DBI-SALA® Self-Rescue Descent System.

**Hazard:** This embrittlement could inhibit the ability of the Self-Rescue Descent System to fully descend an end user in the event of a fall.

**What to do:** Please inspect your 3M™ DBI-SALA® Self-Rescue Descent System's label to confirm if it is P/N 3320030, 3320031 or 3320037 (Refer image below). Once identified, please return the product to the 3M distributor you purchased the product from for a refund or replacement subject to availability.

Alternately contact 3M directly on [3msupport.safety.nz@mmm.com](mailto:3msupport.safety.nz@mmm.com) or 09 477 4040 if you need assistance.

### Contact details:

phone: 09 477 4040

email: [3msupport.safety.nz@mmm.com](mailto:3msupport.safety.nz@mmm.com)

### New Zealand Importer

3M New Zealand Limited  
94 Apollo Drive  
Rosedale, North Shore  
Auckland 0632

Customer Service: 09 477 4040

See [www.recalls.govt.nz](http://www.recalls.govt.nz) for  
other New Zealand consumer product recalls

