

Product Safety Recall



3M™ DBI-SALA® Self-Rescue Descent Systems

P/N 3320030, 332003031 & 332003037

Sold from January 2019 to July 2020

Defect: Embrittlement of the plastic spool used to hold the lifeline rope of the 3M™ DBI-SALA® Self-Rescue Descent System can occur.

Hazard: This embrittlement could inhibit the ability of the Self-Rescue Descent System to fully descend an end user in the event of a fall.

What to Do: Please inspect your 3M™ DBI-SALA® Self-Rescue Descent System's label to confirm if it is P/N 3320030, 3320031 or 3320037 (Refer image below for location of P/N).

If your system is identified as part of the recall with one of the above P/N, please return it to your 3M distributor for a refund or replacement.

Alternately, contact 3M directly on:

3msupport.safety.nz@mmm.com or
09 477 4040



New Zealand Importer:
3M New Zealand Limited

See www.recalls.govt.nz for
other New Zealand consumer product recalls