## Science. Applied to Life.™

## COUNTERFEIT ALERT - NOT A PRODUCT RECALL


April 16, 2021

Dear Valued Customer.


Recently, we have been receiving increasing reports of fraud related to the following three 3M surgical respirator models:

- 3M™ Health Care Particulate Respirator and Surgical Mask 1860;
- 3M™ Health Care Particulate Respirator and Surgical Mask 1860S; and
- 3M<sup>™</sup> Aura<sup>™</sup> Health Care Particulate Respirator and Surgical Mask 1870+.

These have included reports of fake/counterfeit product as well as fraudulent offers where product is offered but not delivered. We have been working with law enforcement to get counterfeit respirators off the market. These enforcement actions have resulted in the seizure of millions of counterfeit model 1860, 1860S, and 1870+ surgical respirators.



- All 3M model 1860, 1860S, and 1870+ respirators imported into the
  United States from any other country are likely to be counterfeit. 3M is not
  currently importing these respirator models into the United States. If you
  have been offered these models coming from outside the United States,
  they should be viewed as counterfeit.
- All 3M model 1860, 1860S, and 1870+ respirators exported from China/ Hong Kong should be viewed as counterfeit. We do not manufacture these respirators in China/Hong Kong.
- Do not rely certification or inspection reports. All shipments of 3M model 1860, 1860S, and 1870+ respirators accompanied by a certification or inspection report are likely counterfeit.
- Beware of fraudulent emails purporting to be from "noreply@mmm.com".
- 3M does not use a "Peru Seal" or other similar seals (examples at right). Respirators bearing these seals are likely counterfeit.



	Lot Codes
Model 1860	B18077, B19029, B19063, B19206, B19240, B19130, B19133, B19155, B19161, B19206, B19314, B19345, B19355, B20010, B20013, B20014, B20016, B20018, B20020, B20021, B20022, B20025, B20035, B20060, B20100, B20119, B20132, B20134, B20235, B20245, B20281, B20670, B20679, B21021, B27233, R12216, R20008, R20025, R20102, R20138, R20144, R20150, R20183, R20190, R20265, R20271, R20294, R20328
Model 1860S	B19791, B20020, B20522, B20541, B20659, B20670, B20679, B20791, R20522, R20545, R20641
Model 1870+	C193041, C190241, C193361, C200771









Please note that there may be counterfeit product with Lot Codes not listed here, and that additional Lot Codes may be added over time.

If you possess respirators bearing one of these Lot Codes, please immediately assess the way in which you acquired those products. If you purchased them from a seller that is not a 3M authorized distributor, then there is a significant risk that they are counterfeit and should not be used. We strongly recommend that 3M respirators be purchased only through 3M authorized distributors, or through existing contracting vehicles (i.e., Federal Supply Schedules), as this will provide the greatest assurance of receiving authentic product.

## Please contact our anti-fraud hotline at 1-800-426-8688 or 3M.com/covidfraud:

- If you are considering an offer for product that raises one or more of these concerns,
- If you have purchased product from a seller who is not a 3M authorized distributor, or that raises one or more of these concerns, and want to authenticate the product,
- To verify whether a seller who is offering or has sold you these products is a 3M authorized distributor, or
- If you have any other questions about model 1860, 1860S, or 1870+ surgical respirators or other 3M respiratory protection products.

You can find more information, including additional tips to help identify counterfeit respirators, on our website at 3M.com/covidfraud.

Thank you for your continued support.