

March 18, 2021 (supersedes January 22, 2021 notice)


Subject: Revised notice: 3M™ Bumpon™ Protective Products backing film change

To Our Valued Customers:

Due to a supplier discontinuation, 3M would like to inform you that we are making a change to the backing film in 3M™ Bumpon™ Protective Products SJ53XX and SJ54XX Series from our US source of supply as well as a list of specific items from our Japan source of supply location.

The backing film is the layer which resides between the rubber bump and the PSA adhesive. 3M has identified and tested a new backing film and confirms the new film has no impact on form, fit or function of the Bumpon protective products. However, the customer will need to determine whether the new product is suitable for their intended application.

Below are images of Bumpon protective products showing the cosmetic difference between the old and new backing films. Without looking at old and new Bumpon protective products side-by-side, it is difficult to detect the slightly darker appearance associated with the new backing film.



3M anticipates it will deplete the current inventory of old backing film and transition to the new film during February 2021. If you have any questions regarding the change, please contact your local 3M sales representative. For reference, the items affected from our Japan source of supply location are listed here.

<u>SKU</u>	<u>Description</u>
<u>JT-2700-0660-7</u>	<u>SJ1005CH CLEAR (3500)</u>
<u>JT-2600-3431-2</u>	<u>SJ1011 CLE(8200)</u>
<u>JT-2700-1211-8</u>	<u>SJ1020C CLEAR (5000)</u>
<u>JT-9400-0087-3</u>	<u>SJ1020C CLEAR(5000) EXP</u>
<u>JT-2600-3620-0</u>	<u>SJ1020CEM BLA(5000)</u>
<u>JT-9400-0384-4</u>	<u>SJ1020CEM BLA3(5000)</u>
<u>JT-2600-4838-7</u>	<u>SJ1020CEM BLA44(5000)</u>
<u>JT-9400-0221-8</u>	<u>SJ1020CEM BLA68(5000)</u>
<u>JT-9400-0222-6</u>	<u>SJ1020CEM GRA17(5000)</u>
<u>JT-2600-4839-5</u>	<u>SJ1020CEM GRAY15(5000)</u>
<u>JT-2600-4840-3</u>	<u>SJ1020CEM IVORY3(5000)</u>
<u>JT-2700-1277-9</u>	<u>SJ1026 CLEAR (8800)</u>
<u>JT-9400-0089-9</u>	<u>SJ1026 CLEAR(8800) EXP</u>
<u>JT-2600-2112-9</u>	<u>SJ1027-1 CLEAR (3000)</u>
<u>JT-2700-2134-1</u>	<u>SJ1037 CLEAR (3000)</u>
<u>JT-2700-0980-9</u>	<u>SJ1038C CLE (7200)</u>
<u>JT-2700-1040-1</u>	<u>SJ1040 CLEAR (450)</u>
<u>JT-2700-1195-3</u>	<u>SJ1042 CLEAR(4200)</u>
<u>JT-9400-0677-1</u>	<u>SJ1042SM CLE (4200)</u>
<u>JT-2600-2565-8</u>	<u>SJ1101C CLE (4660)</u>
<u>JT-2600-4873-4</u>	<u>SJ1415C CLE(425)</u>
<u>JT-2700-2135-8</u>	<u>SJ5008 CLEAR (3000)</u>
<u>JT-2600-2564-1</u>	<u>SJ5008C BLA (3000)</u>
<u>JT-2700-1276-1</u>	<u>SJ5302 CLEAR (3000)</u>
<u>JT-2600-3504-6</u>	<u>SJ5302 CLEAR/SLIT(3000)</u>
<u>70-0707-4321-9</u>	<u>SJ5302A CLEAR (3000) EXP</u>
<u>JT-2700-1291-0</u>	<u>SJ5303 CLEAR (3000)</u>
<u>JT-2700-1979-0</u>	<u>SJ5303H CLEAR (3500)</u>
<u>JT-2700-1275-3</u>	<u>SJ5306 CLEAR (3000)</u>
<u>JT-2700-1976-6</u>	<u>SJ5306H CLEAR (3500)</u>
<u>JT-2700-1274-6</u>	<u>SJ5312 CLEAR (3000)</u>
<u>JT-2700-1978-2</u>	<u>SJ5312H CLEAR (3500)</u>
<u>70070662963</u>	<u>SJ5382 CLEAR(3000)</u>

We thank you for your continued partnership with 3M.

Sincerely,

Dan Holley

Global Portfolio Marketing Manager
3M Electronics Materials Solutions Division