



Immediate Action Required

請立即採取行動

Stop Use/Recall 停止使用/召回



Products 產品:

Select 3M™ DBI-SALA® ShockWave™2 Arc Flash Shock Absorbing Lanyards

部分 3M™ DBI-SALA® ShockWave™2 弧閃緩衝安全繩

Impacted Dates 受影響產品的製造日期:

Prior to June 2022 年 6 月之前

→ 3M Fall Protection is issuing a “Stop Use /Recall” notice for select 3M™ DBI-SALA® ShockWave™2 Arc Flash Shock Absorbing Lanyards. 3M 墜落防護業務部在此發佈 3M™ DBI-SALA® ShockWave™2 弧閃緩衝安全繩的“停止使用/召回”通知



As part of 3M Fall Protection’s ongoing commitment to delivering high quality safety equipment, we are notifying our customers of the following information related to specific 3M™ DBI-SALA® ShockWave™2 Arc Flash Shock Absorbing Lanyards. During an internal review, 3M Fall Protection has identified a potential manufacturing issue with a limited number of devices. **This manufacturing issue could result in the lanyard not performing properly in the event of a fall, which could result in severe injury or death.** Please reference Appendix A for products that are impacted by this notice. There have been no reports of injuries, accidents, or complaints associated with this issue.

3M 墜落防護業務部一直致力於提供高品質的安全防護設備，就部分 3M™ DBI-SALA® ShockWave™2 弧閃緩衝安全繩，我們通知客戶以下訊息。在內部審查過程中，3M 墜落防護業務部發現了有限數量的設備可能存在製造問題。**此製造問題可能導致安全繩在墜落時無法正常運作，從而可能導致重傷或死亡。**本通知涉及的受影響產品請見附錄 A。目前並沒有與此問題相關的受傷、事故或申訴報告。

3M remains committed to providing quality products and services to our customers. We apologize for any inconvenience that this situation may cause you. We appreciate your continued support of 3M Fall Protection products and services.

3M 始終致力於為客戶提供優質的產品和服務。對於這種情況可能給您帶來的不便，我們深表歉意。我們感謝您對 3M 墜落防護產品和服務的持續支援。

End Users 終端使用者

Please follow the steps listed below:



請按照下列步驟操作：

Step 1: Locate the label on the device (see images at right) to determine the model number. If the device is an impacted model (reference Appendix A), remove the product from service.

步驟 1：在設備上找到標籤（見右圖）以確定型號。如果設備是受影響的型號（參見附錄 A），請停止使用該產品。

Step 2: Once you have confirmed the part number, go to www.ShockWaveRecall.com and follow the instructions to return your device. As soon as a replacement product solution is available, 3M will replace your device, as per our standard warranty. Additional details can be found at the website listed above.

步驟 2：確認型號後，請訪問 www.ShockWaveRecall.com 並按照說明退還設備。一旦有替代產品的解決方案可用，3M 將根據我們標準保固條款更換您的設備。有關更多詳細資訊，請訪問上述網站。



Example labels: Above, CSA; Below, ANSI
標籤舉例：上方 CSA 型號；下方 ANSI 型號

Distributors 經銷商

Upon receipt of this Notice, please contact our Customer Service department for a listing of the affected ShockWave™2 Arc Flash Shock Absorbing Lanyards sold to you. If you have any of the affected devices in stock, please return them to 3M Fall Protection for credit at 3M's expense. Please immediately forward this Notice to any of your customers who have purchased affected products from you and provide any assistance requested by your customers to complete the process.

收到此通知後，請聯繫我們的客戶服務部門以獲取您購買的受此影響的 3M™ DBI-SALA® ShockWave™2 弧閃緩衝安全繩清單。如果您的庫存中有任何受此影響的設備，請將其退還給 3M 墜落防護以獲得抵用款，退還費用由 3M 承擔。請立即將此通知轉發給向您購買過受影響產品的任何客戶，並協助客戶完成上述流程。

A copy of this Notice can be found 獲取本通知副本: www.ShockWaveRecall.com.

After visiting www.ShockWaveRecall.com if you still have any questions

訪問 www.ShockWaveRecall.com，如果您還有任何問題

please contact our Customer Service Team:

請聯繫客戶服務團隊

US: Call 1-833-638-2697 or email 3musfpserviceaction@mmm.com

美國：撥打 1-833-638-2697 或郵件 3musfpserviceaction@mmm.com

Canada: Call 1-833-998-2243 or email 3mcafpserviceaction@mmm.com

加拿大：撥打 1-833-998-2243 或郵件 3mcafpserviceaction@mmm.com

3M remains committed to providing quality products and services to our customers. We apologize for any inconvenience that this situation may cause you. We appreciate your continued support of 3M Fall Protection products and services.

3M 始終致力於為客戶提供優質的產品和服務。對於這種情況可能給您帶來的不便，我們深表歉意。我們感謝您對 3M 墜落防護產品和服務的持續支援。

Appendix A: Affected 3M™ DBI-SALA® ShockWave™2 Arc Flash Shock Absorbing Lanyards

附錄 A：受影響的 3M™ DBI-SALA® ShockWave™2 弧閃緩衝安全繩

Date of Manufacture: Prior to June 2022

製造日期：2022 年 6 月之前

Part Number 產品號	Description: 3M™ DBI-SALA® ShockWave™2 Arc Flash Shock Absorbing... 描述:3M™ DBI-SALA® ShockWave™2 弧閃緩衝...	Leg Style 繩腿類型
1224610 1244612 1224612 1244613 1224613 1244615 1244610 1244618	... Lanyard 安全繩	Single Leg 單腿
1244610B		
1244610C 1244637C		
1224611 1244616 1244611 1244617 1244614	... Lanyard, Choker 安全繩，領結扣	Twin Leg 雙腿
1244611B		
1244611C		
1224630 1244632 1224632 1244633 1224633 1244636 1244630 1244639	... 100% Tie-Off Lanyard 100%鉤掛安全繩	Twin Leg 雙腿
1244630B 1244632B		
1244630C 1244641C		
1224631 1244634 1224634 1244635 1244631 1244638	... 100% Tie-Off Lanyard, Choker 100%鉤掛安全繩，領結扣	Twin Leg 雙腿
1244631B 1244634B		
1244631C 1244638C 1244640C		

3M remains committed to providing quality products and services to our customers. We apologize for any inconvenience that this situation may cause you. We appreciate your continued support of 3M Fall Protection products and services.

3M 始終致力於為客戶提供優質的產品和服務。對於這種情況可能給您帶來的不便，我們深表歉意。我們感謝您對 3M 墜落防護產品和服務的持續支援。