

Immediate Action Required



Products: Select Roller Adjuster

3M is issuing this “**Stop Use & Inspect**” notice for select 3M™ DBI-SALA® Cynch-Lok Wood Pole Fall Restriction



As part of 3M’s ongoing commitment to delivering high quality products, we are notifying our customers of the following information related to an issue related to the orientation of the roller adjusters. The potentially affected materials were produced between June 1, 2024 and October 11, 2024. **3M has determined that in the event of a fall and under certain conditions, these devices may not hold the load as expected which could expose the worker to serious injury.** There are no current reports of injuries or accidents related to these materials.

Due to this, we are sending out this Stop Use and Inspect Notice. Any affected products should be removed from service immediately so the inspection can be performed. **Failure to read and follow all instructions associated with this Notice may result in serious injury of a user.** Instructions for appropriate next steps are below, see the appendix for a complete list of models impacted by this stop use/inspect notice.

End Users:

Step 1: Find and inspect the roller adjuster attached to the webbing when the product is oriented as shown below. If the roller is facing towards the termination end, then the product is not affected. If the roller is facing away from the termination end, then the product is affected. Proceed to Step 2.



Check the orientation of the roller adjuster relative to the lanyard's termination end.

Step 2: Contact your distributor to return your product for credit at 3M’s expense.

Distributors:

Upon receipt of this Notice, please contact your 3M Technical Services for a listing of the impacted products sold to you. If you have any of the impacted 3M™ DBI-SALA® Cynch-Lok Wood Pole Fall Restriction in stock, please contact Customer Issue Resolution (3msupport.crcsibgreturns@mmm.com or 1-855-724-4408, option #2) to submit a Return Material Authorization. Customer service

will send you a shipping label to return your affected inventory and provide you credit. Please immediately forward this Notice to any of your customers who have purchased impacted products from you and provide any assistance requested by your customers to complete the process.

Appendix — Part Number List

3M ID	Model Number	Description
70007427217	1200136	3M™ DBI-SALA® Replacement Adjustable Web Positioning Lanyard For Fall Restricting Device 1200136, 6 ft
70007437190	1204075	3M™ DBI-SALA® Wood Pole Adjustable Web Fall Restricting Device 1204075, Distribution Pole
70007428157	1204076	3M™ DBI-SALA® Wood Pole Adjustable Web Fall Restricting Device 1204076, Transmission Pole
70007437208	1204079	3M™ DBI-SALA® Wood Pole Adjustable Web Fall Restricting Device 1204079, Distribution/ Transmission Pole

3M remains committed to providing quality products and services to our customers. We apologize for any inconvenience that this situation may cause you. We appreciate your continued support of 3M Fall Protection products and services. 3M is a trademark of 3M Company.

If you have any questions, please contact our Technical Service Team:

US: Call 1-800-328-6146 or email 3Mfallprotection@mmm.com

Canada: Call 1-800-387-7484 or email 3Mfallprotection-ca@mmm.com



Personal Safety Division

3M Center, Building 235-2W-70
St. Paul, MN 55144-1000

3M PSD products are
occupational use only.

3M Canada

P.O. Box 5757
London, Ontario
N6A 4T1

In United States of America

Technical Service: 1-800-243-4630

Customer Service: 1-800-328-1667

3M.com/workersafety

In Canada

Technical Service: 1-800-267-4414

Customer Service: 1-800-364-3577

3M.ca/Safety

3M is a trademark of 3M. Used under
license in Canada. © 2025, 3M.
All rights reserved. Please recycle.