

Product Description

3M™ Floor Stripper LO Concentrate 22A is a concentrated product to be diluted and dispensed using only the 3M™ Flow Control System Wall Mount Dispenser or the 3M™ Flow Control System Portable Dispenser.

3M™ Floor Stripper LO Concentrate 22H is a concentrated product to be diluted and dispensed using only the 3M™ Twist 'n Fill™ Cleaning Chemical Management System.

3M™ Floor Stripper LO Concentrate 22A and 22H are low-odor floor strippers for use on most resilient tile floors. They are formulated to quickly and effectively remove multiple layers of floor finish and sealer.

Special Features

- Automatic dispensing eliminates measuring and mixing and ensures accurate dilutions
- Effectively softens multiple layers of floor finish for easy removal
- Low-foaming
- Low-odor
- Non-damaging to vinyl

Applications

Remove sealers, floor finish buildup and finishes from resilient floors.

Note: Do not use on wood floors or floorings (such as linoleum) that may be affected by highly alkaline cleaners.

Packaging

3M™ Floor Stripper LO Concentrate 22A

- 0.5-gallon bottle
- 4 bottles per case

Each 0.5-gallon bottle yields 11 ready-to-use gallons.

3M™ Floor Stripper LO Concentrate 22H

- 0.528-gallon bottle
- 6 bottles per case

Each 0.528-gallon bottle yields 11 ready-to-use gallons.

Quick Links

Resource Library Safety Data Sheets (SDS) Video Library

Some of these links lead to web-based resources that are not product-specific.

General Use Directions

Refer to ready-to-use SDS for personal protective equipment (PPE) recommendations.

- Dispense 3M™ Floor Stripper LO Concentrate 22A using the 3M™ Flow Control System Dispenser into a mop bucket.
 - Dispense 3M[™] Floor Stripper LO Concentrate 22H using the 3M[™] Twist 'n Fill[™] Cleaning Chemical Management System into a mop bucket.
- 2. Sweep or dust mop the floor.
- 3. Properly locate caution signs for wet floor conditions.
- Liberally apply the diluted stripper solution with a mop (100 sq. ft./gallon), leaving the floor uniformly wet.

Note: Floors become very slippery when stripper softens finish.

- 5. Allow 5-10 minutes for the stripper to penetrate and soften the finish. Observe the floor and apply additional diluted stripper to areas that may be drying out.
- Use a low-speed floor machine (175 rpm) with the appropriate 3M stripping pad to thoroughly remove the old finish from the floor.
- 7. Pick up the soiled solution with a wet vacuum.
- 8. Flood rinse the floor with clean water and remove with wet vacuum.
- 9. Check dry floor for residue by wiping with dry hand. If residue is observed, repeat step 8 to ensure full removal.
- 10. Inspect floor for any remaining finish and repeat steps 4-9 as necessary to remove fully.
- 11. Mop the floor with a tightly wrung mop of clean water.
- 12. Let the floor dry completely before applying new finish.

Note: If more than 10 coats, contact 3M Rep for ideas on how to quickly remove.

Note: When using an automatic scrubber equipped with the appropriate 3M pad, remember to allow the stripping solution to remain wet on the floor for at least five minutes before agitation and pickup.

Note:

Refer to product Safety Data Sheet for specific physical properties, health hazard, first aid and precautionary information.

- 11-9289-7 (Concentrate)
- 11-9290-5 (RTU)



3M[™] Floor Stripper LO Concentrate 22A and 22H

Precautionary Summary

Do not use on soft metal and plastic surfaces, painted surfaces or other surfaces that are easily scratched.

Health and Safety

When handling any chemical products, read the manufacturers' container labels and the Safety Data Sheets (SDS) for important health, safety and environmental information. To obtain SDS sheets for 3M products, go to <u>3M.com/SDS</u>, or by mail; or in case of an emergency, call 1-888-364-3577 or 1-651-737-6501. When using any equipment, always follow the manufacturers' instructions for safe operation.

Technical Information

Technical information and data, recommendations, and other statements provided by 3M are based on information, tests, or experience which 3M believes to be reliable, but the accuracy or completeness of such information is not guaranteed. Such technical information and data are intended for persons with knowledge and technical skills sufficient to assess and apply their own informed judgment to the information. The typical values shown should not be used for the purpose of specification limits. If you have questions about this Product, contact the **Customer Service Department at 1-800-852-9722.**

Product Use

Many factors beyond 3M's control and uniquely within user's knowledge and control can affect the use and performance of a 3M product in a particular application. Given the variety of factors that can affect the use and performance of a 3M product, user is solely responsible for evaluating the 3M product and determining whether it is fit for a particular purpose and suitable for user's method of application.

Warranty

3M warrants that each 3M product will be free from defects in material and manufacture for 90 days from the date of purchase from 3M's authorized distributor. 3M MAKES NO OTHER EXPRESS OR IMPLIED WARRANTIES, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

Limited Remedy

If a 3M product does not conform to this warranty, the sole and exclusive remedy is, at 3M's option, replacement of the 3M product or refund of the purchase price.

No Extension of Warranty

In the case of an approved warranty claim, the replacement Product will carry only the remaining term of the original warranty period.

Limitation of Liability

Except where prohibited by law, 3M will not be liable for any loss or damage arising from the 3M product, whether direct, indirect, special, incidental or consequential, regardless of the legal theory asserted.

Anchorage

11151 Calaska Circle Anchorage, AK 99515 Telephone: 907-522-5200 Facsimile 907-522-1645

Honolulu

4443 Malaai Street Honolulu, HI 96818 Mail to: P.O. Box 30048 Honolulu, HI 96820 Telephone: 808-422-2721 Facsimile 808-422-9557

Continental United States

Customer Service Department 3M Center Building 223-5S-07 St. Paul, MN 55144-1000 Order Entry 1-800-852-9722 Facsimile 1-800-447-0408

3M Canada

1840 Oxford Street East London, Ontario, Canada N5V 3G2 Mail to: P.O. Box 5757 London, Ontario, Canada N6A 4T1 Telephone: 800-364-3577

Facsimile: 800-364-357



3M Center, Building 220-12E-04 St. Paul, MN 55144



