



**Figure 6**



**Figure 6:** The MBT™ Versatile+ Appliance System increases the buccal root torque (in green) of the upper molars, reducing the possibility of palatal cusp interferences.

**Figure 7**



**Figure 7:** Excessive torque in the posterior segments influences the teeth to roll lingually. The MBT™ Versatile+ Appliance System provides reduced torque values in this area (in green), allowing uprighting of the teeth.