

## Corrosion Protection (Undercoating)

1



### Pre-Cleaning

Pre-wash/clean vehicle prior to disassembly (power wash undercarriage area at repair).


2



### Surface Preparation

Use Scotch-Brite™ Clean N Strip disc to remove loose coatings from the repair area. Use CRS Scotch-Brite™ belt in hard to reach areas.

3



### Clean and Inspect

Blow of area with clean dry compressed air to remove dust and loose surface contaminants. Use a VOC compliant surface cleaner to remove any remaining contaminants. **Note: Coatings must be applied over thoroughly cleaned substrates to maximize corrosion protection.**

4



### Coating Application

Apply appropriate undercoating following local VOC regulations to the area. For maximum corrosion protection apply four medium coats of undercoating allowing flash time between coats.

Visit [www.3m.com.au/aad](http://www.3m.com.au/aad) or [www.3m.co.nz/aad](http://www.3m.co.nz/aad) for more SOPs and videos

## Product List ANZ

3M™ Car Wash Soap Concentrate, 3.78 litre, PN 38377



3M™ All Purpose Cleaner and Degreaser Concentrate, 3.78 litre, PN 38350



Scotch-Brite™ Clean N Strip Disc, PN 57016  
OR  
Scotch-Brite™ Roloc™+ Clean N Strip TR Disc, PN 07466



Scotch-Brite™ Durable Flex Belt, CRS



3M™ Paintable Undercoating Pouch, 162ml, PN08747



3M™ Accuspray™ Spray Gun Kit HGP, PN 16587



## Think About Your Health

3M™ E-A-R™ Skull Screws™ Ear Plug, PN P1300



3M™ Half Facepiece Respirator, PN 07502 with appropriate cartridge



3M™ Lexa™ Protective Eyewear, PN 15200 or 3M Secure Fit AS401SF-AS



Want a product sample or demo, or to speak to a 3M expert? Let us know here: <http://go.3M.com/4AHf>

For ordering information, contact your 3M Sales Representative