



# Scotchlite™

## Vinyl Roll Up Sign Sheeting

### Series RS30

Product Bulletin RS30

July 2002

Replaces PB RS30 dated May 1999

### Health and Safety Information

Read all health hazard, precautionary and first aid statements found in the Material Safety Data Sheet (MSDS), and/or product label of chemicals prior to handling or use.

### Description

3M™ Scotchlite™ Vinyl Roll Up Sign Sheeting Series RS30 consists of retroreflective micro-prisms formed on a flexible glossy and UV-stabilized polymeric film, designed for the production of roll up traffic control signs used in construction work zones. This sign sheeting is designed to provide higher nighttime sign brightness. Series RS30 sheeting has a protective film on the face side. The protective film must be removed before screen processing and is recyclable as classified under SPI Code 1. If the protective film remains on the surface prior to screen processing Series RS30 sheeting does not require solvent cleaning or wiping prior to screen processing. Series RS30 is backed with a heavy duty vinyl coated fabric.

<u>Color</u>	<u>Product Code</u>
White	RS30
Fluorescent	
Orange	RS34

### Prismatic Roll Up Sign Sheeting Requirements

The prismatic retroreflective sheeting used for roll up construction sign blanks shall consist of a high gloss transparent UV-stabilized film bonded to a layer of cube corner prisms and backed with heavy duty vinyl coated fabric. The prismatic roll up sign sheeting shall meet the following specifications:

1. Tensile Strength: 2600 PSI minimum (ASTM D-882)
2. Modulus of Elasticity: 1600 PSI minimum (ASTM D-882)
3. Flexibility: After conditioning a 1" x 6" sample for 24 hours at  $73 \pm 3^\circ\text{F}$  ( $23 \pm 2^\circ\text{C}$ ) and  $50 \pm 5\%$  relative humidity, bend in one second around 1/8" (3.2mm) mandrel with gray side facing the mandrel. There shall be no cracking or crazing.
4. Impact Resistance  
Conditioning: Condition the samples of sealed roll up sign at  $73 \pm 3^\circ\text{F}$  ( $23 \pm 2^\circ\text{C}$ ) and  $50 \pm 5\%$  relative humidity for 24 hours prior to testing.  
Ambient Temperature Impact Resistance: Subject the sheeting to the impact of a 4 lb. (1.82 kg) weight with a 5/8 inch (15.8mm) diameter rounded tip, dropped from the height necessary to generate an impact of 100 inch - lb. as per ASTM D4956. The sheeting shall show no cracking or delamination outside the actual area of impact.  
Cold Temperature Impact Resistance: Subject the sheeting to the impact of a 4 lb. (1.82 kg) weight, with a 5/8" (15.8 mm) diameter rounded tip, dropped from the height necessary to generate an impact of 100 inch - lb. as per ASTM D4956. The sheeting shall show no cracking or delamination outside the actual area of impact.
5. Solvent Resistance: Series RS30 sheeting will not dissolve or pucker when wiped with a soft cloth containing mineral spirits, turpentine, methanol, VM&P Naphtha, or aqueous HCl (5%) or NaOH (5%).
6. Color: The color shall conform to daytime color requirements in Table A when tested in accordance with test methods specified in ASTM E-810 and reported in terms of the CIE 1931 Standard Colorimetric System for

**Table A - Color Specification Limits\*\* (Daytime)  
Chromaticity Coordinates**

Color	1		2		3		4		Reflectance Limit Y (%)
	$\bar{x}$	$\bar{y}$	$\bar{x}$	$\bar{y}$	$\bar{x}$	$\bar{y}$	$\bar{x}$	$\bar{y}$	Min.
White	.303	.287	.368	.353	.340	.380	.274	.316	30.0
Fluorescent Orange	.562	.350	.645	.355	.570	.429	.506	.404	15.0

\*\*The four pairs of chromaticity coordinates determine the acceptable chromaticity on the CIE diagram.

Standard Illuminant D65.

7. Retroreflectivity: When tested in accordance with ASTM E-810 the welded sign blank material shall have the following minimum values of coefficient of retroreflectivity:

Color	(cd/lux/m <sup>2</sup> )		
	Observation Angle (°)	Entrance Angle (-4°)	Entrance Angle (30°)
White	0.2	250	95
	0.5	120	50
	1.0	30	20
Fluorescent Orange	0.2	200	100
	0.5	90	34
	1.0	15	10

8. Accelerated Weathering: Retention of 50% of reflective intensity minimum requirements after 250 hours when tested in accordance with ASTM G23 Type E or EH with humidity off.

### Fabrication Guidelines

**A.** As supplied, Roll Up Sign Sheeting Series RS30 includes a plastic protective film which must be removed prior to fabricating the sign. The protective film can be easily lifted by bending the sign at a corner or seam. Screen processing should be completed within 24 hours of removing the plastic film.

**Note:** Removal of the protective film may generate static electricity and should not be done in the presence of flammable solvents.

**B.** Series RS30 sheeting is designed for sewing or riveting corner pockets or snaps. Cross brace supports can then be used in conjunction with portable sign stands. All corner pockets and washers should be nylon, rubber, or plastic materials. Avoid using hardware or mounting brackets with sharp edges.

**C.** Separate overlay (copy/symbol) pieces can be attached to roll up signs using 3M™ Dual Lock™ Reclosable Fasteners SJ3543 Type 250 Stems or Scotchmate™ Hook and Loop Fastening Systems SJ3526 Loop with SJ3527 Hook. Prepare the sheeting surface by cleaning with an IPA (alcohol) cleaning spray to remove dirt and other surface contaminants. Peel the protective liner off the fastener and apply with firm roll down pressure to assure complete adhesive contact on the sheeting. Apply at temperatures above 68°F.

If the product is expected to perform in environments below 20°F, sewing of the overlay pieces using an industrial sewing machine is highly recommended.

### D. Screen Processing

Screen processing should be done within 24 hours of removing the protective film. The off contact screen process method is the preferred screening method for roll up sign sheetings. The screening table must be perfectly flat. When screening the roll up sheets, hold the sheets in place using a vacuum table or if a vacuum table is not available, the sheets can be held in place on a non-porous table surface using a thin, uniform layer of low tack pressure sensitive adhesive. The screen mesh size should be in the PE 157 - PE 175 range of monofilament fabric. A sharp squeegee of medium or hard rubber is recommended.

Stenciling the process colors or use of other screen fabric mesh sizes may not produce satisfactory color or durability and are not recommended.

### NOTE:

3M™ Scotchlite™ Process Black Ink 1805 is the recommended screen printing ink for RS30 roll up sheeting. Use CGS50 for thinning the 1805 ink. For a full color palette, 3M™ Scotchlite™ Process Color Series 990 may also be used on series RS30 sheeting. These inks must be coated with 4430R clear. The 4430R can be applied after 2 hours of drying of series 990 ink. Screen printed sheets must be dry for 24 hours (on drying rack) before rolling up or attaching the pockets.

See Product Bulletin 1800 or call 3M Technical Services at 1-800-553-1380.

#### **D. Storage**

Unprocessed Scotchlite sheeting should be stored in a cool, dry area, preferably at 65°-75°F (18°-24°C) and 30-50% relative humidity, and should be used within one year after the purchase.

**Unprocessed sheets** should be **stored flat** as packaged and supplied. The protective film should remain on the sheeting until it will be processed.

See Information Folder 1.11 for details of storage and packaging. Finished roll up signs should be stored dry and rolled up properly per sign manufacturer specifications.

#### **General Performance Considerations**

The durability of RS30 sign sheeting will depend upon preparation, compliance with recommended application procedures, geographic area, exposure conditions, and maintenance. Maximum durability of RS30 sheeting can be expected in applications subject to vertical exposure when processed according to 3M recommendations provided in Information Folder 1.7.

## **Literature Reference**

#### **Screen Processing**

Scotchlite™ Process Colors	PB 1800
Scotchlite™ Process Colors	PB 990
Scotchlite™ Process Colors	PB 4400
Scotchlite™ Process Colors Application Instruction	IF 1.8

#### **Application**

Cutting, Matching, Premasking & Prespacing Instructions	IF 1.10
---	---------

#### **Storage and Packaging**

Storage Maintenance and Removal Instructions	IF 1.11
--	---------

#### **FOR INFORMATION OR ASSISTANCE**

##### **CALL:**

**1-800-553-1380**

##### **Fax-on-Demand in the U.S. and Canada:**

**1-800-887-3238**

##### **Internet:**

**[www.3M.com/tcm](http://www.3M.com/tcm)**

3M assumes no responsibility for any injury, loss or damage arising out of the use of a product that is not of our manufacture. Where reference is made in literature to a commercially available product, made by another manufacturer, it shall be the user's responsibility to ascertain the precautionary measures for its use outlined by the manufacturer.

**Important Notice**

All statements, technical information and recommendations contained herein are based on tests we believe to be reliable, but the accuracy or completeness thereof is not guaranteed, and the following is made in lieu of all warranties, express or implied. Seller's and manufacturer's only obligation shall be to replace such quantity of the product proved to be defective. Neither seller nor manufacturer shall be liable for any injury, loss or damage, direct or consequential, arising out of the use of or the inability to use the product. Before using, user shall determine the suitability of the product for his/her intended use, and user assumes all risk and liability whatsoever in connection therewith.

Statements or recommendations not contained herein shall have no force or effect unless in an agreement signed by officers of seller and manufacturer.



**Traffic Control Materials Division**

3M Center, Building 225-5S-08  
P.O. Box 33225  
St. Paul, MN 55133-3225

**3M Canada Company**

P.O. Box 5757  
London, Ontario N6A 4T1

**3M México, S.A. de C.V.**

Av. Santa Fe No. 55  
Col. Santa Fe, Del. Alvaro Obregón  
México, D.F. 01210



*40% Pre-consumer waste paper  
10% Post-consumer waste paper*

© 3M 2002 75-0301-0662-1