ANZ Standard Operating Procedures Paint Finishing and Detailing

Paint Finish Full Panel Process



Initial Defect Removal Texture Match

DA sand the repair area with a P1500/P2000 3M™ Purple Finishing Film Hookit™ Disc or P1500 3M™ Trizact™ Clearcoat Sanding Disc used damp. Remove all paint defects and match texture to adjacent OEM panels. Wipe panel clean.



Scratch Refinement 3000


Refine the P1500/P2000 scratches with a DA and a 3000 3M™ Trizact™ Hookit™ Foam Disc used damp with a 3M[™] Hookit[™] Soft Interface Pad. Wipe panel clean. Inspect the surface for rogue 1500 scratches using the 3M™ SUN GUN™ II Light Kit.





Scratch Refinement 5000 (Optional)

To reduce your buffing time refine the 3000 scratches with a DA and a 5000 grit 3M™ Trizact™ Hookit™ Foam Disc used damp with a 3M™ Hookit™ Soft Interface Pad. Wipe panel clean. The use of 3000 is required prior to 5000 for best results. Inspect the surface using the $3M^{\text{TM}}$ SUN GUN $^{\text{TM}}$ II Light Kit.



Compound

Compound the repair area with a high speed polisher set between 1200-2000 RPM. For faster results, use a foam compounding pad and the appropriate rubbing compound. To insure all sand scratches have been removed, inspect the surface using the 3M™ SUN GUN™ II Light Kit.





Machine Polish

Polish the repair area with a high speed polisher set between 1200-2000 RPM. Use a black foam polishing pad and the appropriate machine polish. Wipe the panel clean with a yellow microfiber cloth. Inspect the surface using the $3M^{\mbox{\tiny TM}}$ SUN GUN™ II Light Kit.





Ultra ine Machine Polish (Optional)

Polish the repair area with a high speed polisher with the speed set between 1200-2000 RPM. Use a blue foam polishing pad and the appropriate ultrafine machine polish. Leave a light film of the polish on the panel and wipe clean with a blue microfiber cloth.

Final Detail

Remove any masking material from the repair area and clean any residual sling from adjacent panels and door jamb areas. Cleaning the panel immediately after compounding and polishing will greatly improve the ease of cleaning. Inspect the surface using the 3M™ SUN GUN™ II Light Kit.

Visit www.3M.com.au/aad or www.3m.co.nz/aad for more SOPs and videos

Product List ANZ

3M™ Purple Finishing Film Hookit™ Disc, 150mm, P1500, PN 51145; P2000, PN 30666

3M™ Trizact™ Hookit™ Clearcoat Sanding Disc, 150mm, P1500, PN 02088

3M™ Soft Interface Pad, 150mm x 5mm PN 50545 150mm x 10mm PN 50544

3M™ Trizact™ Hookit™ Foam Disc, 150mm, 3000, PN 02085; 5000, PN 30662

3M™ Perfect-It™ EX Rubbing Compound, 946ml, PN 36060

3M[™] Perfect-It[™] Foam Compounding Pad, Double Sided, Quick Connect, 203mm, PN 05706

3M™ Perfect-It™ Low Linting 100% Wool Compound Pad, Double Sided, Quick Connect, PN 33279

3M™ Quick Connect Adaptor, 14mm. Thread, PN 33271

3M™ Perfect-It™ EX Machine Polish, 946ml, PN 06094

3M™ Perfect-It™ Foam Polishing Pad, Double Sided, Quick Connect, 203mm, PN 05707

3M™ Perfect-It™ EX Ultrafine Machine Polish, 946ml, PN 06068

3M™ Perfect-It™ Ultrafine Foam Polishing Pad, Double Sided, Quick Connect, 203mm, PN 05708

3M™ Perfect-It™ Detail Cloth, PN 06020

3M™ SUN GUN™ II Light Kit, PN 16550

3M[™] Perfect-It[™] Clean and Shine, 473ml bottle, PN 06084























Think About Your Health

3M™ E-A-R™ Skull Screws™ Ear Plug, PN P1300



3M™ Half Facepiece Respirator, PN 07502 with appropriate cartridge



3M™ Lexa™ Protective Eyewear, PN 15200 or 3M Secure Fit AF421SF-AS

Want a product sample or demo, or to speak to a 3M expert? Let us know here: http://go.3M.com/4AHf