





Quick Setup Guide


3M™ PELTOR™ Professional In-Ear Communication Headset, PIC-100











Steps

- 1. Insert Battery
- 2. Attach Eartips
- 3. Connect Headset
- 4. Attach System Contol Unit (SCU)
- 5. Insert Left and Right Earplugs
- 6. Press Power
- 7. Find Noise and Fit Test

For complete instructions on the use and care of the 3M™ PELTOR™ Professional In-Ear Communication Headset, please refer to the User Instructions. Please read, understand, and follow all safety information in the User Instructions prior to use. For additional information or any questions, contact 3M Technical Services in the U.S. at 1 (800) 243-4630 and Canada at 1 (800) 267-4414.