

April 11, 2011



**PRODUCT ADVISORY NOTICE:**  
**Incorrect Standards Markings**  
**3M™ Peltor™ MultiVisor™ Systems**

Dear 3M Customer:

This notice is to inform you of incorrect standard compliance markings for various Peltor MultiVisor Systems.

**V1B Thin Mesh Black Nylon Visor**

A recent audit of this product revealed that the dimensions of the visor window fall short of the coverage requirements specified in section 10.2.1 of CSA Z94.3-2007 - Eye and Face Protectors.



The lower rounded corners of the faceshield do not cover the sharp lower corners of the trapezoid specified in the standard (see picture at left). Accordingly, these visors do not meet CSA Z94.3-2007.

However, the visor does meet all the requirements of ANSI Z87.1-2003 – Occupational and Educational Personal Eye and Face Protection Devices Standard for a basic impact face shield. As a result of our findings, we will be replacing the “CSA Z94.3” mark on the product with “Z87.1.”

The products affected are:

3M Stock Number	Description
XH001651534	3M™ Peltor™ MultiVisor™ Thin Mesh Black Nylon Visor, 10 each/case
70071522406	3M™ Peltor™ LumberJack™ with XLR8™ Hard Hat 6PT/ P/L, V1B, H31P3E, 1 each/case

If these visors are in use in your facility and you require that these visors meet all CSA Z94.3 requirements, we recommend selecting a different visor to meet that need. Please contact Dawn Toon at 1-508-721-0429 or dawn.toon@mmm.com for replacement product or additional information.

### V3C, V3CS, V4E, V4F, and V4FS Polycarbonate Visors

For the V3C, V3CS, V4E, V4F, and V4FS visor for hard hat assemblies, ANSI Z87.1-2003- Occupational and Educational Personal Eye and Face Protection Devices Standard compliance has been changed. Recent testing indicates that these visor assemblies do not meet the High Impact Testing Requirements, Section 9.3.1.2, of ANSI Z87.1-2003. Therefore, these products cannot be marked with a "Z87.1+". However, the products comply with Basic Impact Testing Requirements, Section 9.2.2 of ANSI Z87.1-2003 and, therefore, can be marked with a "Z87".

The 3M product numbers for the V3C, V3CS, V4E, V4F, and V4FS polycarbonate visors affected by this Product Advisory Notice are as follows:

3M Stock Number	Description
XH001652953	3M™ Peltor™ V3C MultiVisor™ Short Clear Polycarbonate
70071522679	3M™ Peltor™ V3CS MultiVisor™ Clear Polycarbonate, Anti-Static
XH001650288	3M™ Peltor™ V4F MultiVisor™ Clear Polycarbonate
XH001650346	3M™ Peltor™ 4F Clear Polycarbonate Visor Replacement
XH001651617	3M™ Peltor™ V4E MultiVisor™ Green Polycarbonate
XH001651427	3M™ Peltor™ 4E Green Polycarbonate Visor Replacement
NA	3M™ Peltor™ V4FS MultiVisor™ Clear Polycarbonate, Anti-Static

If you need a visor that provides protection according to the High Impact Testing Requirements of ANSI Z87.1-2003, we recommend selecting a different visor to meet that need. Please contact Dawn Toon at 1(508) 721-0429 or dawn.toon@mmm.com for replacement product or additional information.

We apologize for any confusion or inconvenience caused by these issues. Thank you for your support.

Regards,



Richard Morris  
US Business Director



Robert Weber  
Manager of Quality, Regulatory,  
and Technical Services