

Certificate of Compliance

Certificate Number **20110819-R9269B**
Report Reference **2011 August 19**
Issue Date **2011 August 19**

Page 1 of 2



Issued to: **3M Company**

3M Center
St Paul, MN 55144

*This is to certify that
representative samples of*

Firestop Devices

3M Fire Barrier Putty Sleeve Kit
(Manufactured in United States of America)

SEE ADDENDUM PAGE 2

Have been investigated by Underwriters Laboratories Inc.® (UL) or any authorized licensee of UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: ANSI/UL 1479, "Fire Tests of Through-Penetration Firestops,"

Additional Information: See UL On-Line Certification Directory at www.UL.com for additional information.

Only those products bearing the UL Classification Mark should be considered as being covered by UL's Classification and Follow-Up Service.

The UL Classification Mark includes: UL in a circle symbol:  with the word "CLASSIFIED" (as shown); a control number (may be alphanumeric) assigned by UL; a statement to indicate the extent of UL's evaluation of the product; and, the product category name (product identity) as indicated in the appropriate UL Directory.

Look for the UL Classification Mark on the product

William R. Carney

Director, North American Certification Programs

Underwriters Laboratories Inc.

Any information and documentation involving UL Mark services are provided on behalf of Underwriters Laboratories Inc. (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://www.ul.com/global/eng/pages/corporate/contactus/>

Certificate of Compliance

Certificate Number **20110819-R9269B**
Report Reference **2011 August 19**
Issue Date **2011 August 19**

Page 2 of 2



This is to verify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

3M Fire Barrier Putty Sleeve Kit DT 100, DT 200 and DT 400 fire stop device for use in Through Penetration Firestop System Nos. C-AJ-0134, C-AJ-3310, W-L-0036, W-L-0037, W-L-3371, W-L-3372.

William R. Carney

Director, North American Certification Programs

Underwriters Laboratories Inc.

Any information and documentation involving UL Mark services are provided on behalf of Underwriters Laboratories Inc. (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://www.ul.com/global/eng/pages/corporate/contactus/>