
3M Automotive Aftermarket Division

Third Party Recommendations, Approvals, & Endorsements



into Every Repair

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Runge To	- 11111
cc	2009-2012	All	М	AN .	All	
Eco	2007 - 2012	All	All	-	All	111111
e, Rabit, OTI,	2006 - 2012	All	All	AR	All	1 1111
RSI	2005 - 2012	All	AB	All	A1	1 11111
tsa SportWagen	2000 - 2014	All	All	All	All	4 1000
New Beetle, NB Convertible	1998 - 2010	All	40	All	All	1 1111
Passet, Passet Wagon	2006 - 2011	All		A4	All	3 1111
Phaston	2006	All	All	AB	AS	7 1111
Tiguan	2008 - 2012	All	AR	All	All	1 1111
Touareg. Touareg 2	2004 - 2012	All	All			- 1111
Customer Str To avoid unnot the windshiel Customer ma Streak or Do not ci Chatter of Technia If addresse The followl The case	y compain that wis smaar. ear across entire lier is skip as wiper brain Cal Backgro d, the wiper performing causes are posar is wash and care pro-	pers are ineffective. Ingith of blade, Ingith across windshie DUNC! Thance is significant place: DUUC!s leave wax re	complains may aid glass. ay improved, as is sidues as well as	the longevity of the	wiper blades.	II 9368

Everyday, engineers and technicians around the world choose 3M products as the best solution for their manufacturing and repair needs. From Specifications and Endorsements to Service Bulletins and Recall Notices, 3M is proud to be a trusted partner of the Automotive Industry.

Here's just one example...



Reference Information

Organization: Volkswagen Group of America, Inc.

Document

Type: Technical Bulletin

Name: Customer States Windshield Wipers Streak or Smear

Number: 92 11 02

Issued: April 14, 2011

Description

2009-2012 2005-2012 Jetta, Jetta SportWagen 2006 Phaeton Vehicles: 2008-2012 2007-2012 1998-2012 New Beetle, New Beetle Convertible Eos Tiguan 2006-2012 Touareg, Golf, Rabbit, 2006-2011 Passat, Passat Wagon 2004-2012 GTI. R32 Touareg 2

Purpose:

This bulletin address a customer concern that the windshield wipers streak or smear. The customer complaint may include that the wipers streak or smear, do not clear across the entire length of the blade, or chatter or skip as the wiper travels across the windshield glass. To avoid unnecessary replacement of wiper blades, a few potential causes such as the condition and cleanliness of the windshield and wiper blades should be checked first. The following causes are also possible: car wash/care products leave wax residues and remnants of high gloss drying aid on all glass surfaces, Nano coating was used on the windshield and rear glass, the rubber sections of the blade are worn.

Note:

3M provides this information for REFERENCE ONLY.

ALWAYS refer to the original document or the OEM-provided model-specific collision damage repair manuals for complete instructions.

3M Products:

Included: PN38070 3M™Perfect-It™III Cleaner Clay

PN38113 3M™Perfect-It™ Gloss Enhancer

Note: In sor

In some cases, 3M may offer an alternate part number (different size/color) with the same chemistry and/or performance as the included product. Please consult your 3M Representative for more information.

Source:

erWin.vw.com

www.Collision.ALLDATA.com

Product Use:

Many factors beyond 3M's control and uniquely within user's knowledge and control can affect the use and performance of a 3M product in a particular application. Given the variety of factors that can affect the use and performance of a 3M product, user is solely responsible for evaluating the 3M product and determining whether it is fit for a particular purpose and suitable for user's method of application.

Warranty, Limited Remedy, and Disclaimer:

Unless an additional warranty is specifically stated on the applicable 3M product packaging or product literature, 3M warrants that each 3M product meets the applicable 3M product specification at the time 3M ships the product. 3M MAKES NO OTHER WARRANTIES OR CONDITIONS, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OR CONDITION OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE OR ANY IMPLIED WARRANTY OR CONDITION ARISING OUT OF A COURSE OF DEALING, CUSTOM OR USAGE OF TRADE. If the 3M product does not conform to this warranty, then the sole and exclusive remedy is, at 3M's option, replacement of the 3M product or refund of the purchase price.

Limitation of Liability:

Except where prohibited by law, 3M will not be liable for any loss or damage arising from the 3M product, whether direct, indirect, special, incidental or consequential, regardless of the legal theory asserted, including warranty, contract, negligence or strict liability.



Automotive Aftermarket Division Building 0223-06-N-01 St. Paul, MN 55144-1000 3MCollision.com

3M is a trademark of 3M.
Please Recycle. Printed in the U.S.A.
© 3M 2012. All rights reserved.
1-877-MMM-CARS (877-666-2277)