



Scotch-Weld™ Low Odour Acrylic Adhesive DP8805NS Green

Product Data Sheet

Date: December 2016
Supersedes: October 2016

Product Description

3M™ Scotch-Weld™ Low Odour Acrylic Adhesives are high performance, two-part acrylic adhesives with lower odour than most acrylic adhesives. These toughened products feature improved shear, peel and impact performance. These durable products feature a fast rate of strength build, providing structural strength in minutes.

Key Features

- Adhesion to many plastics and metal
- Toughened
- Work life of approximately 4 minutes
- Good shear strength
- Structural strength in about 10 minutes
- High peel strength
- 10:1 mix ratio
- Increased cure speed with applied heat
- Contain glass beads (250µ diameter) to control bond line thickness

Note:

Unless otherwise indicated, all properties measured at 22 °C.

Physical Properties

Property	DP8805NS Green	
Colour	Base (B) Accelerator (A)	Off-white Blue
Viscosity ¹	Base (B) Accelerator (A)	45000 mPas 15000 mPas
Density ²	Base (B) Accelerator (A)	1,06 g/cm ³ 1,08 g/cm ³
Mix ratio	By volume By weight	10 Parts B : 1 Part A 10 Parts B : 1 Part A
Note: Cure speed times are approximate and depend on adhesive temperature.		
Work life ³		3-5 min
Open time ⁴		4-6 min
Time to handling strength ⁵		6-8 min
Time to structural strength ⁶		8-10 min
Full cure time		24 hours

1. Viscosity measured using parallel plate viscometer; reported viscosity at 4 sec⁻¹ shear rate.

2. Density measured using pycnometer.

3. Maximum time that adhesive can remain in a static mixing nozzle and still be expelled without undue force on the applicator.

4. Maximum time allowed after applying adhesive to one substrate before bond must be closed and fixed in place.

5. Minimum time required to achieve 0,35 MPa of overlap shear strength.

6. Minimum time required to achieve 6,9 MPa of overlap shear strength.

Environmental Resistance¹⁰

Condition	Substrate	DP8805NS Green
150 °C	Aluminium	100 %
50 °C + 80 % relative humidity		60 %
85 °C + 85 % relative humidity		50 %
Water		70 %
Salt water (5 w t% in water)		70 %
Diesel fuel		100 %
Motor oil		100 %
Antifreeze (50 wt % in water)		85 %
Isopropyl alcohol		50 %
Bleach (10 wt% in water)		60 %
50 °C + 80 % relative humidity		PVC
Water	100 %	
Salt water (5 wt % in water)	100 %	
Sulphuric acid (16 wt % in water)	100 %	
Sodium hydroxide (10 wt % in water)	90 %	

10. Values indicate overlap shear test performance retained after 1,000 hours of continuous exposure relative to a control sample left at room temperature; samples conditioned for 24 hours at room temperature and 50% relative humidity prior to tests; "NT" = not tested yet.

Note: Fully-cured Low Odour Acrylic Adhesives can withstand short-term incidental contact with almost any solvent, chemical, or environmental condition. However, long-term continuous exposure to the following liquids should be avoided:

1. Elevated temperature (>37°C) water
2. Ketone-type solvents (acetone, MEK)
3. Gasoline and similar liquids

Directions For Use

1. To obtain the highest strength structural bonds, paint, oxide films, oils, dust, mould release agents, and all other surface contaminants must be completely removed. The amount of surface preparation depends on the required bond strength and environmental aging resistance desired by user. For suggested surface preparations on common substrates, see the section on surface preparation.

2. Mixing

For Duo-Pak Cartridges

Store cartridges with cap end up allowing any air bubbles to rise towards the tip. To use, simply insert the cartridge into the EPX applicator and start the plunger into the cylinders using light pressure on the trigger. Then remove the cap and expel a small amount of adhesive to ensure material flows freely from both sides of cartridge. For automatic mixing, attach an EPX mixing nozzle to the cartridge and begin dispensing the adhesive. For hand mixing, expel the desired amount of adhesive and mix thoroughly. Mix approximately 15 seconds after obtaining a uniform colour.

For Bulk Containers

Mix thoroughly by weight or volume in the proportion specified on the product label or in the typical uncured properties section. Mix approximately 15 seconds after obtaining a uniform colour.

3. Apply adhesive and join surfaces within the open time listed for the specific product.

Larger quantities and/or higher temperatures will reduce this working time.

4. Allow adhesive to cure at 16 °C or above until completely firm. Applying heat up to 66 °C will increase cure speed.

5. Keep parts from moving during cure. Apply contact pressure or fixture in place if necessary. Optimum bond line thickness ranges from 0.005 to 0.020 inch; shear strength will be maximized with thinner bond lines, while peel strength reaches a maximum with thicker bond lines.

6. Excess uncured adhesive can be cleaned up with ketone type solvents.*

***Note: When using solvents, extinguish all ignition sources, including pilot lights, and follow the manufacturer's precautions and directions for use.**

Surface Preparation

3M™ Scotch-Weld™ Acrylic Adhesives are designed to be used on metal, wood and most plastic surfaces. The following cleaning methods are suggested for common surfaces:

Steel:

1. Wipe free of dust and dirt with pure solvent such as acetone or isopropyl alcohol.*
2. Sandblast or abrade using clean fine grit abrasives.
3. Wipe again with clean solvent to remove loose particles.*
4. When using a primer, apply within 4 hours after surface preparation.

Aluminium:

1. Wipe free of dust and dirt with pure solvent such as acetone or isopropyl alcohol.*
2. Sandblast or abrade using clean fine grit abrasives.
3. Wipe again with clean solvent to remove loose particles.*

Plastics/Rubbers:

1. Wipe with isopropyl alcohol.*
2. Abrade using fine grit abrasives.
3. Wipe with isopropyl alcohol.*

Glass:

1. Solvent wipe surface using acetone or MEK.*
2. Apply a thin coating of a silane adhesion promoter to the glass surfaces to be bonded and allow to dry completely before bonding.

***Note: When using solvents, extinguish all ignition sources, including pilot lights, and follow the manufacturer's precautions and directions for use.**

Storage & Shelf Life

Store product at 27 °C or below. Refrigeration at 4 °C will help extend shelf life. Do not freeze. Allow product to reach room temperature prior to use.

The product can be stored up to 18 months after production.

Note: The shelf life may be shortened if the original packaging is not properly sealed or stored in an environment with high temperatures or humidity.

Precautionary Information

Refer to product label and Material Safety Data Sheet for health and safety information before using the product.
For information, please contact your local 3M Office.
www.3M.com

For Additional Information

To request additional product information or to arrange for sales assistance, call.....
Address correspondence to: 3M

Important Notice

All statements, technical information and recommendations contained in this document are based upon tests or experience that 3M believes are reliable. However, many factors beyond 3M's control can affect the use and performance of a 3M product in a particular application, including the conditions under which the product is used and the time and environmental conditions in which the product is expected to perform. Since these factors are uniquely within the user's knowledge and control, it is essential that the user evaluate the 3M product to determine whether it is fit for a particular purpose and suitable for the user's method or application. All questions of liability relating to this product are governed by the terms of the sale subject, where applicable, to the prevailing law

Values presented have been determined by standard test methods and are average values not to be used for specification purposes. Our recommendations on the use of our products are based on tests believed to be reliable but we would ask that you conduct your own tests to determine their suitability for your applications. This is because 3M cannot accept any responsibility or liability direct or consequential for loss or damage caused as a result of our recommendations

3M United Kingdom PLC
2M Centre, Cain Road, Bracknell
RG12 8HT
United Kingdom

3M Ireland Ltd
The Iveagh Building, 3rd Floor
The Park, Carrickmines 18
Ireland

3M Belgium bvba/sprl
Hermeslaan 7
1831 Diegem
Belgium

3M Nederland B.V.
Molengraaffsingel 29
2629 JD Delft
The Netherlands

3M Svenska AB
Herrjärva torg 4
170 67 Solna
Sweden

3M a/s
Hannemanns Allé 53
DK-2300 Copenhagen S.
Denmark

3M Norge AS
Tærudgata 16
2004 Lillestrøm
Norway

Suomen 3M Oy
Keilaranta 6
02150 Espoo
Finland

3M Eesti OÜ
Pärnu mnt. 158
11317 Tallinn
Estonia

3M Latvia SIA
K.Ulmaņa gatve 5
Rīga, LV-1004
Latvia

3M Lietuva UAB
A.Goštauto g. 40
Vilnius LT- 03163
Lithuania