

Replacement of inlay and molar crown using 3M™ Lava™ Esthetic Fluorescent Full-Contour Zirconia

Clinical dentistry and photography by: Dr. Gunnar Reich, Munich, Germany
Lab work by: MDT Nicole Freund, Tutzing, Germany

About the Case:

52-year old female patient with a fractured glass ceramic inlay at tooth #35 and a chipped porcelain fused-to-zirconia crown at tooth #36.



Initial situation: Fractured glass ceramic inlay at tooth #35 and chipped porcelain fused-to-zirconia crown at tooth #36.



Initial situation – buccal view.



Chipped zirconia crown is removed.



Preparations.



Final situation: 3M™ Lava™ Esthetic Fluorescent Full-Contour Zirconia inlay and crown, shade C1, finished with stain and glaze. Inlay and crown both cemented with 3M™ RelyX™ Ultimate Adhesive Resin Cement.



Final situation – buccal view.